




Replacement of coupling fast-release valve type SKU 03415 and type SKU 03420

E-mail: service@gok-online.de
Service hotline: +49 9332 404 774

Series with following codes
are affected:

01.2016	06.2016	10.2016
02.2016	07.2016	11.2016
03.2016	08.2016	12.2016
04.2016	09.2016	01.2017
05.2016		



Example: code is 10.2016

Turn the ring for a
better reading of the code.



GOK

Regler- und Armaturen-Gesellschaft mbH & Co. KG · **Obernreiter Straße 2-18 · 97340 Marktbreit / Germany**
Tel.: 09332 404-0 · Fax: 09332 404-49 · E-Mail: info@gok-online.de · www.gok-online.de · www.gok-blog.com